

3/9/2020

ERR Recap

Overall they were happy with our design. They want all of our files of drawing, video, and data collection.

In discussion they suggested a simpler design. Use turnbuckles instead of linear actuators. Also to help with testing we switched from a 12v DC system to a 110V 3 phase motor. Another way to move feed gap plate instead of a crank.

With these inputs we had to change our design to fit the motor and electrical system.

Meeting with Dev at 1 pm to find out what we can use. Meet with Loren to buy bulk of the material.