




THE BEAST



Team Meeting #9

Monday, July 15, 2019

AGENDA

| <u>Topic</u> | <u>Item</u> | <u>Resolution</u> |
|---------------------|--|---|
| Old Business | | |
| New Business | | |
| Example | <ol style="list-style-type: none"> Control System (Chris) POC Wheel Hub (Will) | <ol style="list-style-type: none"> Fix out of control motor using coding first before hardware fix. Test limiting the input. Test correction. Learned that 12V really isnt a problem for little motors. Noted tolerance issues with POC. Specifically loose connector hole allows spring to angle fits. Next item to do FBD to verify Bolt and other specs. |