

Team Meeting-10/30/14

Minutes:

1. Sleep mode is not working. Bug fixes in progress.
2. PCB design in building stage.
3. Microcontroller implementation on PCB in work.