

Team Meeting #16

01/29/20

Motor

- No box
- Cantilever issue
- Swenson's Thoughts
- Opt. 1

- Opt. 2

Stepper Motors

- Meet with Hefeida tomorrow
- Swenson believes the issue is voltage

Cutter

- Must move down
- Linear actuator to high
- Motor should be covered

Total Model

- Add where to place electronics
- Must be accessible
- Must be able to access rollers

Wheel Size

- Potentially look for a smaller option
- Need to determine necessity

Moment Problem

- Oval flange bearing
- Need to determine size

Action Items

- Linear Actuator Code and Circuit – Alyssa
- Encoder Determination – Kyle
- Modeling – Rennie/Ian
- Assembly – Ian/Rennie