




# THE BEAST



Mentor Meeting #7

Tuesday, July 30, 2019

## AGENDA

<u>Topic</u>	<u>Item</u>	<u>Resolution</u>
--------------	-------------	-------------------

### Old Business

### New Business

1. Snapshot 2 (Nick)
2. Plasma Cutting (Will)

1. Dr. Swenson likes slides and plan overall with the exception of the following suggestions: Remove the graphic from the BMP image, Change "Suspension" to "Wheel Assembly," Move schedule items to table, insert snippet from budget.
2. Cut brackets were received. Notable features are rough cut and there is significant amounts of slag on the surface. Dr. Swenson suggests buffing the slag off. Noted by Nick and Will that Jake has agreed to help with milling operations.