

Large Drill Press Cleaning Procedure

- 1. Clean all tools and place back into proper locations**
- 2. From top to bottom, use the hand broom to brush all large shavings off machine onto the floor**
- 3. Use rag to soak up oil and coolant**
- 4. Sweep up shavings off of floor**
- 5. Vacuum all remaining shavings (on and off machine)**
- 6. If oil or coolant is spilled on the floor mop around machine.**
- 7. Scan 360 degrees around machine and repeat steps if necessary**

