



## Mentor Meeting #9

Monday, 09/09/2019

## **AGENDA**

Topic <b>Business</b>	<u>ltem</u>	<u>Resolution</u>		
Example	Ι,	Status of BOM (Will)	I.	Rods for Wheel Hub Assembly axels are
	2.	Staus of Electrical Modeling (Chris)		too hard of steel, so softer 3/4" axel rods will need to be ordered and added to the budget.
			2.	Electrical Modeling has been completed. Can be viewed in the One Drive.