

# **Cooling Tower Loop**

\_\_\_\_\_\_

# Fluid

f1\$ = 'Steam<sub>IAPWS</sub>'

# First Law Analysis of Loop 1

$$\dot{Q}_{CT} = \dot{W}_{CTP,1} + \dot{Q}_{Cond}$$

# **Pump**

$$\dot{W}_{CTP,1} = 18.99 \text{ [kW]} \cdot \left| 3412 \cdot \frac{\text{Btu/hr}}{\text{kW}} \right|$$

$$\dot{\mathbf{W}}_{\text{CTP},1} = \dot{\mathbf{m}}_1 \cdot [\mathbf{h}_3 - \mathbf{h}_2]$$

# Condenser

$$\dot{Q}_{Cond} = \dot{m}_1 \cdot [h_1 - h_3]$$

# State 1

$$T_1 = 81.6$$
 [F]

$$x_1 = 0$$
 Assumption

$$h_1 = h [f1\$, T=T_1, x=x_1]$$

$$P_1 = P[f1\$, T=T_1, x=x_1]$$

#### State 2

$$x_2 = 0$$
 Assumption

$$P_2 = P[f1\$, x = x_2, h = h_2]$$

$$T_2 = T [f1\$, x = x_2, h = h_2]$$

# State 3

$$T_3 = 72.3$$
 [F]

$$x_3 = 0$$
 Assumption

$$h_3 = h[f1\$, T=T_3, x=x_3]$$

$$P_3 = P[f1\$, T = T_3, x = x_3]$$

# Loop 2

\_\_\_\_\_\_

# Fluid

f2\$ = 'R134a'

# First Law Analysis of Loop 2

$$\dot{Q}_{Evap} + \dot{W}_{Comp,1} = \dot{Q}_{Cond}$$

# Compressor

Power = 234.2 [kW] 
$$\cdot$$
 3412  $\cdot$  Btu/hr kW

 $\dot{W}_{Comp,1}$  = Power ·  $\eta_{Comp}$ 

 $\eta_{Comp} = 0.87$  Place Holder

$$\dot{\mathbf{W}}_{\text{Comp,1}} = \dot{\mathbf{m}}_2 \cdot [\mathbf{h}_4 - \mathbf{h}_7]$$

#### Condenser

$$\dot{Q}_{Cond} = \dot{m}_2 \cdot [h_4 - h_5]$$

# Evaporator

$$\dot{Q}_{Evap} = \dot{m}_2 \cdot [h_7 - h_6]$$

# State 4

$$T_4$$
 = Average [ 97.1 [F], 96.7 [F], 97.4 [F], 96.6 [F]]

$$h_4 = h [f2\$, T = T_4, P = P_4]$$

$$x_4 = x [f2\$, T = T_4, P = P_4]$$

# State 5

$$P_5 = P_4$$

$$T_5 = T [f2\$, P=P_5, h=h_5]$$

$$x_5 = x [f2\$, P=P_5, h=h_5]$$

#### State 6

$$P_6 = P_7$$

$$T_6 = T [f2\$, P=P_6, h=h_6]$$

$$x_6 = x [f2\$, P=P_6, h=h_6]$$

State 7

 $T_7$  = Average [ 33.2 [F], 35 [F], 33.2 [F], 33.8 [F]]  $P_7$  = Average [ 35 [psia], 34.7 [psia], 35.3 [psia], 35.5 [psia]]  $x_7$  =  $\mathbf{x}$  [f2\$, T=T<sub>7</sub>, P=P<sub>7</sub>]  $h_7$  =  $\mathbf{h}$  [f2\$, T=T<sub>7</sub>, P=P<sub>7</sub>]

# Loop 3

# Chilled Water Loop

\_\_\_\_\_\_

# Fluid

f3\$ = 'Steam<sub>IAPWS</sub>'

# Evaporator

$$\dot{Q}_{Evap} = \dot{m}_3 \cdot [h_8 - h_9]$$

# State 8

$$T_8 = 54.2$$
 [F]

 $x_8 = 0$  Assumption

Flow = 802 [GPM] 
$$\cdot$$
 8.021  $\cdot$   $\frac{\text{ft}^3/\text{hr}}{\text{GPM}}$ 

$$\rho = \rho [f3\$, T = T_8, x = x_8]$$

$$\dot{m}_3 = Flow \cdot \rho$$

$$h_8 = h [f3\$, T = T_8, x = x_8]$$

$$P_8 = P [f3\$, T = T_8, x = x_8]$$

#### State 9

$$T_9 = 40.9$$
 [F]

$$x_9 = 0$$
 Assumption

$$h_9 = h [f3\$, T = T_9, x = x_9]$$

$$P_9 = P[f3\$, T = T_9, x = x_9]$$

# Unit Settings: Eng F psia mass deg

 $\eta_{\text{Comp}} = 0.87$  f2\$ = 'R134a'

Flow =  $6433 \text{ [ft}^3/\text{hr]}$ 

 $\dot{m}_2 = 72574 [lb_m/hr]$ 

Power = 799123 [Btu/hr]

 $\dot{Q}_{CT} = 6.113E + 06$  [Btu/hr] {509.4 [Ton]}

 $\rho = 62.39 [lb_m/ft^3]$ 

 $\dot{W}_{\text{CTP,1}} = 64797 \text{ [Btu/hr] } \{18.99 \text{ [kW]}\}$ 

f1\$ = 'Steam\_IAPWS'
f3\$ = 'Steam\_IAPWS'
m1 = 651064 [lb<sub>m</sub>/hr]
m3 = 401345 [lb<sub>m</sub>/hr]
Qcond = 6.048E+06 [Btu/hr] {504 [Ton]}
QEVAP = 5.353E+06 [Btu/hr] {446 [Ton]}

 $\dot{W}_{Comp,1} = 695237 [Btu/hr] \{203.8 [kW]\}$ 

No unit problems were detected.

# **KEY VARIABLES**

 $\dot{Q}_{Evap}$  = 5.353E+06 [Btu/hr] {446 [Ton]}  $\dot{W}_{Comp,1}$  = 695237 [Btu/hr] {203.8 [kW]}

 $\dot{m}_3 = 401345 [lb_m/hr]$ 

 $\dot{m}_1 = 651064 [lb_m/hr]$ 

 $\dot{m}_2 = 72574 \ [lb_m/hr]$ 

Capacity of a single chiller.

Work input to the compressors.

Flow Rate

Flow Rate

Flow Rate

#### **Arrays Table: Main**

	$T_{i}$	$P_{i}$	h <sub>i</sub>	$\mathbf{x_i}$
	[F]	[psia]	[Btu/lbm]	
1	81.6	0.5346	49.66	0
2	72.2	0.3915	40.27	0
3	72.3	0.3929	40.37	0
4	96.95	98.75	118.3	100
5	70.42	98.75	34.92	-100
6	22.74	35.13	34.92	0.1791
7	33.8	35.13	108.7	100
8	54.2	0.208	22.27	0
9	40.9	0.1261	8.937	0