

Background

Currently TDRC processes over 2700 fittings a day. These are individually placed onto cleaning racks. Manual sorting of the fittings accounts for 65% of the operator time required for cleaning fittings.

Problem Statement

Design a sorting system that dramatically reduces the amount of manual sorting time required by the operators. Demonstrate a solution for two fittings (3/8" union and 3/8" sleeve). Identify any 3rd party commercial parts available.

1.000": 4,823

Sleeves/yr: Unions/yr: 0.250": 204,589 0.250": 38,717 0.375": 288,209 0.375": 97,174 0.500": 71,185 0.500": 18,043 0.625": 43,383 0.625": 13,005 0.750": 31,386 0.750": 11,341

1.000": 17,867




3/8" Sleeve and Union





(Left) Racking basket for cleaning; (Right) Rack staging area; (Below) Cleaning process.




Titanium Fitting Sorting






Solution Concept



Working Prototype




University of Idaho


College of Engineering




Special thanks to Jeff Williams of Vista Outdoors, Bill Magnie, Dr. Anderson, Dr. Beyerlein, Alex Olson and Coleton Bailey.




3/8" Sleeve Sorting Process




3/8" Union Sorting Process





Inline Stage

Vertical Stage




Rotation Stage



Selected geometry forces fittings to move to inline.

Machined rails allow fittings to queue for racking while also keeping them vertical.





Racking fixture prevents fittings from falling off and guides rack fingers into fittings.